

# Oil Field Environmental Incident Summary

**Incident:** 20160620154901      **Date/Time of Notice:** 06/20/2016 15:49  
**Responsible Party:** CONTINENTAL RESOURCES, INC.  
**Well Operator:** CONTINENTAL RESOURCES, INC.  
**Well Name:** NORFOLK 3-1H  
**Field Name:** NORTH TOBACCO GARDEN      **Well File #:** 23087  
**Date Incident:** 6/20/2016      **Time Incident:** 13:30      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 151      **Rng:** 99      **Sec:** 1      **Qtr:**  
**Location Description:** Prairie just south of well pad

**Submitted By:** NATE STANHOPE      **Received By:**  
**Contact Person:** DARREL BERGLUND  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Pasture      **Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Gallons	1	Gallons	1	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 12/20/2016      **Clean Up Concluded:** 6/20/2016

**Risk Evaluation:**

N/A

**Areal Extent:**

10 ft. x 20 ft. area burned on location. 10 ft. x 10 ft. area burned off well pad.

**Potential Environmental Impacts:**

Grass

**Action Taken or Planned:**

Fire was immediately extinguished by CLR operator.

**Wastes Disposal Location:** N/A

**Agencies Involved:**

**Updates**

---

**Date:** 6/20/2016    **Status:** Reviewed - Follow-up Required

**Author:** Schiermeister, Robin

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spill went off site. Follow-up required.

---

**Date:** 7/11/2016    **Status:** Inspection

**Author:** Schiermeister, Robin

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site 7-7-16 at 3:29. Fire occurred south of the well pad, and they had stockpiled the contaminated soil nearby. Further follow-up is needed to check for vegetation and to see if stockpiled soil has been removed.